Michael O. Leavitt Governor

Kathleen Clarke Executive Director Lowell P. Braxton Division Director

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801 801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

NSPECTION REPORT

Exploration: Partial: X Complete: Inspection Date & Time: April 25, 2000, 9:15 to 11:15 AM Date of Last Inspection: March 10, 2000

Mine Name: Hiawatha Complex County: Carbon Permit Number: ACT/007/011

Permittee and/or Operator's Name: Hiawatha Coal Company Business Address: P. O. Box 1202, Huntington, Utah 84528

Type of Mining Activity: Underground X Surface Prep. Plant Other

State Officials(s): Paul Baker Company Official(s): Elliott Finley

Federal Official(s): None

Weather Conditions: Clear, 60's, still some snow on north-facing slopes in Middle Fork Existing Acreage: Permitted-12707 Disturbed-290 Regraded- Seeded- Bonded-290 Increased/Decreased: Permitted-<u>0</u> Disturbed-<u>0</u> Regraded-<u>0</u> Seeded-<u>0</u> Bonded-<u>0</u> Status: \_Exploration/X Active/\_Inactive/\_Temporary Cessation/\_Bond Forfeiture

Reclamation ( Phase I/ Phase II/ Final Bond Release/\_Liability\_Year)

# REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

#### Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - b. For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below. 2.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]		[X]	$\Box$
2.	SIGNS AND MARKERS			Ц	
3.	TOPSOIL	Ξ	ĹĬ	$\Box$	$\Box$
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]	$\Box$	[X]	$\Box$
Ъ.	SEDIMENT PONDS AND IMPOUNDMENTS		П	Ц	$\Box$
c.	OTHER SEDIMENT CONTROL MEASURES	Ū	$\Box$	Ц	$\Box$
d.	WATER MONITORING	Ц	$\Box$	$\Box$	$\Box$
e.	EFFLUENT LIMITATIONS				
5.	EXPLOSIVES	$\Box$	$\Box$	$\Box$	Ц
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	$\Box$	$\Box$	$\Box$	Ц
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	$\Box$	$\Box$	$\Box$	Ц
8.	NONCOAL WASTE		$\Box$	$\Box$	
9.	PROTECTION OF FISH, WILDLIFE AND				
	RELATED ENVIRONMENTAL VALUES	$\Box$	Ц	Ц	П
10.	SLIDES AND OTHER DAMAGE		$\Box$		
11.	CONTEMPORANEOUS RECLAMATION	$\Box$	$\Box$	$\Box$	П
12.	BACKFILLING AND GRADING	Ц	$\Box$	$\Box$	П
13.	REVEGETATION	[X]		[X]	П
14.	SUBSIDENCE CONTROL		$\Box$	$\Box$	П
15.	CESSATION OF OPERATIONS		$\Box$	$\Box$	$\Box$
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	$\Box$	$\Box$	П	Ц
b.	DRAINAGE CONTROLS	$\Box$	$\Box$	Ц	Ц
17.	OTHER TRANSPORTATION FACILITIES		$\square$		ŢŢ
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	$\Box$	П		
19.	AVS CHECK (4th Quarter-April, May, June)_(date)	$\Box$	ĹĴ	$\Box$	ŢŢ
20.	AIR QUALITY PERMIT	$\Box$	$\square$	$\Box$	ГŢ
21.	BONDING & INSURANCE	ĨΧΊ	[]	[X]	Ш

#### INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: ACT/007/011

DATE OF INSPECTION: April 25, 2000

### (Comments are Numbered to Correspond with Topics Listed Above)

#### 1. Permits, Change, Transfer, Renewal, Sale

The response to Division Order 97A the Division received March 20, 2000, was approved April 20, 2000. This completes the requirements of this Division Order. It will probably be necessary for the operator to make changes to some drainage control structures, and I have identified some changes that have been made in the plan. I will be checking these over the next few months.

## 4. Hydrologic Balance

#### a. Diversions

I have had some concerns about drainage control in areas at the South and Middle Fork coal stockpile areas. At each of these, there has been an area where runoff was able to flow uncontrolled down a steep hill toward the truck loadout. The operator has constructed berms to try to solve this problem.

In South Fork, the berm should work to keep water from going down the hill, but it would also pond a small amount of water. It would be better if, in addition to the berm, the operator did a little grading to get water to flow toward DD46.

The area near the Middle Fork loadout was still wet from melting snow, so the operator was only able to do a limited amount of grading. The berm that was built in this area is small enough I don't think it would survive a season of thunderstorms. Like the loadout in South Fork, it appears the best solution would be to grade the area so water would flow toward the ditch on the south side of the stockpile area. The berm should work temporarily.

# 13. Revegetation

There are two areas that were graded and seeded last fall, and we saw numerous seedlings in these areas.

Another area was graded a few years ago but was mistakenly not seeded. This area was also seeded last fall, but most seedling we saw in this area were Russian thistle. There were a few grasses, but it was hard to see them.

Another area on top of slurry pond 5 was graded last fall and seeded a few weeks ago. This is the area I've been encouraging the operator to seed for the last few months. According to Mr. Finley, there was still some snow in most gouges when it was seeded, but we could not see any seedlings.

Kochia is a very aggressive annual weed that, until this inspection, I had not seen at Hiawatha. We saw several small seedlings.

I encourage the operator to begin now to control musk thistle. The plants are still rosettes, so they would be difficult to see, but they are much easier to dig or spray this time of year.

Whitetop is best controlled by spraying just before it blooms, and this time is coming soon.

### 21 Bonding and Insurance

Mr. Finley showed me a copy of the new certificate of insurance, and it meets Division requirements.

Copy of this Report:

Mailed to: Elliott Finley (Hiawatha Coal Co.), James Fulton (OSM)

Given to: Pamela Grubaugh-Littig (DOGM)

Inspector's Signature:

Baker #41

Date: May 3, 2000